

WICHITA FALLS CULTURAL RESOURCES SURVEY
 WICHITA COUNTY HERITAGE SOCIETY
 SURVEY FORM

NAME OF SITE: _____ ADDRESS: 2314 10th

LEGAL DESCRIPTION: Subdivision Floral Heights Block _____ Lot _____

PRESENT OWNER: _____

and MAILING ADDRESS: _____

CATEGORY: District _____ Building X Structure _____ Site _____ Object _____

ORIGINAL USE: residential PRESENT USE residential ZONING _____

PHYSICAL DESCRIPTION: One-story wood frame residence; irregular shape with double gable roof; end chimney; open framing on porch gable repeats house roofline; framing repeated on side of porch; shingles cover front gable and skirt around foundation; 2 bay with single front door.

MATERIALS: wall wood frame/shingles roof composition _____

CONDITION OF EXTERIOR: good

ALTERATIONS/ADDITIONS: none visible

ARCHITECTURAL STYLE/TYPE AND SIGNIFICANCE: Bungalow - open gable framing of porch particularly interesting on this small bungalow.

SIGNIFICANT PERSONS AND EVENTS ASSOCIATED WITH SITE:

RELATIONSHIP TO SURROUNDINGS: In area that is predominantly residential in character; on busy street.

CURRENT TAX ASSESSMENTS:

Year	Land	Improvements	Total
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

PRESENT DESIGNATION: _____

RECOMMENDED DESIGNATION: National Register _____ Registered Texas Landmark _____

Local Landmark _____

If within a district: Significant _____ Contributing _____ Compatible _____ Intrusion _____

-2-

OTHER COMMENTS/OBSERVATIONS:

SOURCES OF INFORMATION:

PHOTO DATA: Roll 8 Frame 11

RECORDED BY: Ellen Beasley

Date March, 1982

Much of the information above may be transferred directly to survey cards of the Texas Historical Commission. The following information would need to be added, using the THC computer codes, to complete the State cards:

COUNTY: _____

PERIOD: _____

CITY: _____

STYLE: _____

DATE: _____

THEME: _____

CODED SITE NUMBER: _____

EB 8/81

