

WICHITA FALLS CULTURAL RESOURCES SURVEY
 WICHITA COUNTY HERITAGE SOCIETY
 SURVEY FORM

NAME OF SITE: Bristol-Teer ADDRESS: 106 Pembroke
 LEGAL DESCRIPTION: Subdivision #28-Part #6 Morningside Park Block Lot
 PRESENT OWNER: J. E. Teer
 and MAILING ADDRESS: 106 Pembroke
 CATEGORY: District ☒ Building Structure Site Object
 ORIGINAL USE: residence PRESENT USE residence ~~ZONING~~
 PHYSICAL DESCRIPTION: One-story rectangular plan with gable roof. Paired fenestration-
8 over 1 sash. Arched entrance with gable overhang. One exterior front chimney. Side
porch with brick pillars and half-timbering in gable end. Garage apartment.
 MATERIALS: wall brick roof composition shingles
 CONDITION OF EXTERIOR: excellent
 ALTERATIONS/ADDITIONS: None discernible.
 ARCHITECTURAL STYLE/TYPE AND SIGNIFICANCE: Bungalow Influence
 SIGNIFICANT PERSONS AND EVENTS ASSOCIATED WITH SITE: Built 1925.
 RELATIONSHIP TO SURROUNDINGS: Part of scene.
 CURRENT TAX ASSESSMENTS:

Year	Land	Improvements	Total
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>

PRESENT DESIGNATION:
 RECOMMENDED DESIGNATION: National Register Registered Texas Landmark
 Local Landmark ☒
 If within a district: Significant Contributing ☒ Compatible Intrusion

-2-

OTHER COMMENTS/OBSERVATIONS:

SOURCES OF INFORMATION:

PHOTO DATA: Roll 1 Frame 17RECORDED BY: Ellen Beasley; Susan H. Campbell Date March, 1982

Much of the information above may be transferred directly to survey cards of the Texas Historical Commission. The following information would need to be added, using the THC computer codes, to complete the State cards:

COUNTY: _____ PERIOD: _____
CITY: _____ STYLE: _____
DATE: _____ THEME: _____
CODED SITE NUMBER: _____

EB 8/81



COUNTY QUAD BLOCK
CITY LOT 10
#28-Part #6 Morningstar Park

NAME: Bristol-Teer
ADDRESS: 106 Pembroke
COUNTY: Wichita
CITY: Wichita Falls
UTM: _____
DATE: 1925 PERIOD: 1900-
STYLE: Bungalow Influence
THEME: _____

ARCHITECT/BUILDER: _____
OWNER: J. E. Teer

DESCRIPTION: One-story rectangular plan with gable roof. Paired fenestration - 8 over 1 sash. Arched entrance with gable overhang. One exterior front chimney. Side porch with brick pillars and half-timbering in gable end. Garage apartment.

BUILDING MATERIAL: wall: Brick roof: Composition shingles
PHYSICAL CONDITION: Excellent SITE: original ☒ or moved _____ date _____
ALTERATIONS: _____
SIGNIFICANCE: _____

AREA OF SIGNIFICANCE: _____ LEVEL OF SIGNIFICANCE: _____
DESIGNATION: NR NHL RTHL HABS HAER HESI HSI OTHER:
ORIGINAL USE: Residence PRESENT USE: Residence
RELATIONSHIP TO SURROUNDINGS: _____
ACREAGE/BOUNDARY DESCRIPTION: _____

BIBLIOGRAPHIC DATA: _____
SEE INFO/CORRESPONDENCE FILES: _____
RECORDED BY: Susan H. Campbell INFORMANT: OWNER
DATE: _____ PHOTO DATA: _____

(rev. 6-79)