

WICHITA FALLS CULTURAL RESOURCES SURVEY
WICHITA COUNTY HERITAGE SOCIETY
SURVEY FORM

No. on Master List: 357

NAME OF SITE: Tarry ADDRESS: 129 Pembroke
LEGAL DESCRIPTION: Subdivision #2 Morningside Park North Block Lot
PRESENT OWNER: Mrs. J. P. Tarry
and MAILING ADDRESS: 129 Pembroke
CATEGORY: District ☒ Building Structure Site Object
ORIGINAL USE: residence PRESENT USE residence ZONING
PHYSICAL DESCRIPTION: Two-story Southern Colonial, white, Columned portico, large landscaped grounds with statuary.

MATERIALS: wall brick roof composition shingle
CONDITION OF EXTERIOR: excellent
ALTERATIONS/ADDITIONS: None discernible.

ARCHITECTURAL STYLE/TYPE AND SIGNIFICANCE: Southern Colonial Revival

SIGNIFICANT PERSONS AND EVENTS ASSOCIATED WITH SITE: Built circa 1939.

RELATIONSHIP TO SURROUNDINGS: Part of scene.

CURRENT TAX ASSESSMENTS:

Year	Land	Improvements	Total
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>

PRESENT DESIGNATION:

RECOMMENDED DESIGNATION: National Register Registered Texas Landmark

Local Landmark ☒

If within a district: Significant Contributing ☒ Compatible Intrusion

-2-

OTHER COMMENTS/OBSERVATIONS:

SOURCES OF INFORMATION:

PHOTO DATA: Roll 1 Frame 34RECORDED BY: Ellen Beasley; Susan H. Campbell Date March, 1982

Much of the information above may be transferred directly to survey cards of the Texas Historical Commission. The following information would need to be added, using the THC computer codes, to complete the State cards:

COUNTY: _____ PERIOD: _____

CITY: _____ STYLE: _____

DATE: _____ THEME: _____

CODED SITE NUMBER: _____

EB 8/81



18a

COUNTY QUAD BLOCK LOT # 2 M.P. NORTH

NAME: TARRY COUNTY: Wickham

ADDRESS: 129 Pembrooke CITY: Wickham Falls

ARCHITECT/BUILDER: _____ DATE: c. 1939 ? PERIOD: 1900 -

OWNER: Mrs. J.P. Tarry STYLE: Southern Colonial Revival

THEME: _____

DESCRIPTION: Two-story Southern Colonial white, columned portico, large landscaped grounds with statuary

BUILDING MATERIAL: wall: _____ roof: composition shingle

PHYSICAL CONDITION: excellent SITE: original ☒ or moved _____ date _____

ALTERATIONS: _____

SIGNIFICANCE: _____

AREA OF SIGNIFICANCE: _____ LEVEL OF SIGNIFICANCE: _____

DESIGNATION: NR NHL RTHL HABS HAER HESI OTHER: _____ PRESENT USE: Residence

ORIGINAL USE: Residence

RELATIONSHIP TO SURROUNDINGS: _____

ACREAGE/BOUNDARY DESCRIPTION: _____

BIBLIOGRAPHIC DATA: _____

SEE INFO/CORRESPONDENCE FILES: _____

RECORDED BY: _____ INFORMANT: owner

DATE: _____ PHOTO DATA: _____ (rev. 6-79)